

Re: Chen project (2306-261)
Verification of TPZ regarding Tree 509

As shown in the drawing (Page A102), the TPZ is within the dripline of T 509. However, it doesn't encroach more than the 25% guideline by the International Society of Arboriculture.

The tree protection zone/fencing shown on page A102 is correct as determined by the project arborists and will be installed as outlined by the project arborists.

The project arborist will inspect the installation of the tree protection fencing before excavation or clearing.

That stated the project arborist is to be on-site during site lot clearance involving T 509, to ensure the proper trimming of any roots that may be encountered.

Respectfully Submitted

Neal Baker



10/24/24

ArboristsNW.com

ISA Cert. PN1075A

TRAQ ISA (Tree Risk Assessment Qualified)

