


Text	Page	Responses
<p>Existing and proposed sector mounts do not show the same locations for the P3.0 pylons. Provide more detail on how these mounts could be adjustable without changes to the attachment to base structure, or provide the modifications to base structure including details and calculations.</p>	<p>1</p>	<p>CD S-pages show the proposed mounting layout, which will utilize the existing Posts/Roof connections. A standoff is being added to the existing posts to skew the face to the desired rad centers. No new Roof attachments are used here.</p> 

To whom it may concern,

Please see responses above and reach out if you have any questions!

Alexander Bazeley, P.E.
Structural Lead | Core One Consulting USA
4515 S. McClintock Drive, Suite 220, Tempe, AZ 85282
(M) (727) 798-4974

(E) alex.bazeley@coreoneconsulting.com