



City of Mercer Island Property Hazard Report

Site Address: 8818 SE 62ND ST

Parcel #: 8650500045

Report Generated on February 6, 2025

Potential Slide:

Steep Slope:

No Hazard Found

No Hazard Found

Erosion:

Seismic:

No Hazard Found



Wind Speed Up Values 1.0 1.3 1.6 1.9

~~Wind Exposure:~~

No Hazard Found



These maps are for the use of City of Mercer Island staff for the purposes of permit application evaluation. It provides a general assessment of known or suspect hazard areas for which the City will require site and project specific evaluation by a Washington State licensed engineer, geologist or engineering geologist prior to issuing a site for development. All areas have not specifically evaluated for hazards and there may be locations that are not correctly represented on these maps. It is the responsibility of the property owners and map users to evaluate risk associated with their proposed development. No site-specific assessment of risk is implied or otherwise indicated by the City of Mercer Island by these maps.