







	Location of New Pole		Critical Areas
	Parcel		Stream
	Right of Way		Stream Buffer/Setback
	Tree Inventory		Geological Erosion Area
			Potential Landslide Hazard

**FIGURE 1: SITE MAP
W. MERCER WAY & SE
32ND ST**



FIGURE 2: POLE DIAGRAM

